# **VMware Deliverable Release Notes**



This document does not apply to HPE Superdome servers. For information on HPE Superdome, see the following links:

<u>HPE Integrity Superdome X</u> <u>HPE Superdome Flex</u>

Information on HPE Synergy supported VMware ESXi OS releases, HPE ESXi Custom Images and HPE Synergy Custom SPPs is available at:

VMware OS Support Tool for HPE Synergy

Information on HPE Synergy Software Releases is available at:

HPE Synergy Software Releases - Overview

### Gen11 SPP 2023.04.00.00 Release Notes for VMware ESXi 8.0

BIOS (Login Required) - System ROM

Driver - Lights-Out-Management

Driver - Storage Controller

Firmware - Network

<u>Firmware - Storage Controller</u> <u>Firmware - Storage Fibre Channel</u>

Software - Management

<u>Software - Storage Fibre Channel</u> Software - System Management

# Driver - Lights-Out Management

Top

HPE iLO Native Driver for ESXi 7.0 Version: 10.8.0 (Recommended)

Filename: ilo-driver\_700.10.8.0.6-10EM.700.1.0.15843807\_20300719.zip

### <u>Fixes</u>

• Fixed issue where ilo driver is failing to acquire contiguous physical memory below 4GB causing userworld apps like honcfg to be unable to communicate with iLO.

#### **Enhancements**

Added support for vSphere 8.0

# **Driver - Storage Controller**

Top

HPE ProLiant Gen11 Smart RAID Controller Driver for VMware vSphere 8.0 (Bundle file)

Version: 80.4380.0.108 (Recommended)

Filename: Microchip-smartpqi 80.4380.0.108-10EM.800.1.0.20613240 20828555.zip

# **Enhancements**

Gen11 PR2,2023 March MSB Usage

#### Firmware - Network

<u>Top</u>

Mellanox Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter: HPE part numbers

P31246-B21 and P31246-H21

Version: 16.35.1012 (Recommended)

Filename: 16\_35\_1012-MCX515A-CCA\_HPE\_Ax.pldm.fwpkg

### **Important Note!**

For PLDM enabled VPI (Virtual Protocol Interconnect) adapters supporting both InfiniBand mode and Ethernet modes, every firmware version is made available in two different formats at HPE.com:

- 1. HPE signed PLDM Firmware Package (.FWPKG filename extension) updatable via iLO.
- 2. Firmware binary (.bin filename extension) updatable via mstflint utility from the Operating System.

Choose the appropriate firmware file format based on your preference and what suits your environment.

**Disclaimer**: Certain software including drivers and documents may be available from NVIDIA. If you select a URL that directs you to <a href="http://www.nvidia.com/">http://www.nvidia.com/</a>, you are then leaving HPE.com. Please follow the instructions on <a href="http://www.nvidia.com/">http://www.nvidia.com/</a> to download NVIDIA software or documentation. When downloading the NVIDIA software or documentation, you may be subject to NVIDIA terms and conditions, including licensing terms, if any, provided on its website or otherwise. HPE is not responsible for your use of any software or documents that you download from <a href="http://www.nvidia.com/">http://www.nvidia.com/</a>, except that HPE may provide a limited warranty for NVIDIA software in accordance with the terms and conditions of your purchase of the HPE product or solution.

A list of known issues with this release is available

#### **Prerequisites**

FWPKG will work only if the firmware version flashed on the adapter is 16.27.1016 or later and iLO5 firmware version must be 2.30 or higher.

#### **Fixes**

#### The following issues have been fixed in version 16.35.1012:

- RDE (Redfish) PATCH operation to LLDPTransmit properties "ManagementAddressIPv4", "ManagementAddressIPv6" and "ManagementAddressMAC" were applied only in the first attempt, but failed in the next.
- PLDM AEN event receiver media was changed unexpectedly and destination BDF was overridden with garbage when some PLDM packet were received from the SMBus layer.
- Bad configuration of number of VFs and SFs led to the consumption of too many functions and triggered a FW assert 0x888E. The reduction flows behavior was fixed to ensure the configuration does not exceed the total number of supported functions.
- InfiniBand L2 QP could not receive RDMA traffic occasionally.
- Running with a debug firmware reduced security as if token was applied.

### **Enhancements**

Important: Security Hardening Enhancements - This release contains important reliability improvements and security hardening enhancements. HPE recommends upgrading your device firmware to this version to improve the firmware security and reliability of your device.

### New features and changes included in version 16.35.1012:

- Added support for copy modify header steering action to/from the UDP field.
- Enabled ADP timer to allow the user to configure RC or DC qp\_timeout values lower than 16.
- QoS priority trust default state can now be changed using the new nvconfig below:

QOS\_TRUST\_STATE\_P1
QOS\_TRUST\_STATE\_P2
The values that can be used to set the default state are:
TRUST\_PORT
TRUST\_PCP
TRUST\_DSCP
TRUST\_DSCP PCP

# **Supported Devices and Features**

This software package contains the following firmware versions:

Melianox Ethernet Only Adapters	Firmware Version	PSID
HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter(P31246-B21 and P31246-H21)	16.35.1012	MT_0000000591

# Firmware - Storage Controller

<u>Top</u>

Online ROM Flash Component for VMware ESXi - HPE Smart Array E208e-p SR Gen10 on Gen11 servers

Version: 5.32 (C) (Recommended)

Filename: CP053948.compsig; CP053948.zip

### **Enhancements**

Add Gen11 servers into support list

### Firmware - Storage Fibre Channel

Top

HPE Firmware Flash for Emulex 32Gb and 64Gb Fibre Channel Host Bus Adapters

Version: 14.0.499.29 (Recommended) Filename: P14.0.499.29\_header.pldm.fwpkg

# **Important Note!**

This Firmware package contains following firmware versions:

Adapter	Speed	Universal Boot Image	Firmware	UEFI	Boot Bios
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0

# **Enhancements**

This Firmware package contains following firmware versions:

Adapter	Speed	Universal Boot Image	Firmware	UEFI	<b>Boot Bios</b>
HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter	32Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Single Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0
HPE SN1700E 64Gb Dual Port Fibre Channel Host Bus Adapter	64Gb	14.0.499.29	14.0.499.29	14.0.499.2	14.0.490.0

# **Supported Devices and Features**

This component is supported on following Emulex Fibre Channel Host Bus adapters:

# 32Gb Fibre Channel Host Bus Adapter:

- HPE SN1610E 32Gb Single Port Fibre Channel Host Bus Adapter
- HPE SN1610E 32Gb Dual Port Fibre Channel Host Bus Adapter

# **64Gb Fibre Channel Host Bus Adapter:**

- HPE SN1700E 64Gb Dual port Fibre Channel Host Bus Adapter
- HPE SN1700E 64Gb Single port Fibre Channel Host Bus Adapter

#### Software - Management

<u>Top</u>

HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 8.0

Version: 2022.09.01 (**Recommended**) Filename: cp051152.compsig; cp051152.zip

### **Enhancements**

Supports VMware ESXi 8.0

HPE iLO Driver Bundle Smart Component for ESXi 7.0

Version: 2022.09.01 (**Recommended**) Filename: cp050763.compsig; cp050763.zip

# <u>Fixes</u>

• Fixed issue where ilo driver is failing to acquire contiguous physical memory below 4GB causing userworld apps like hponcfg to be unable to communicate with iLO.

# **Enhancements**

Added support for vSphere 8.0

HPE QLogic Fibre Channel driver component for VMware vSphere 8.0

Version: 2023.03.01 (**Recommended**) Filename: cp054352.compsig; cp054352.zip

# **Important Note!**

This component is intended to be used by HPE applications. It is a zip that contains the same driver deliverable available from the vmware.com and the HPE vibsdepot.hpe.com webpages, plus an HPE specific CPXXXX.xml file.

### **Prerequisites**

Please consult SPOCK for a list of supported configurations available at the following link:

http://www.hpe.com/storage/spock/

# **Enhancements**

Driver version 5.3.1.0

# Supported Devices and Features

This component is supported on following Qlogic Fibre Channel Host Bus adapters:

# 32Gb Fibre Channel Host Bus Adapter:

- HPE SN1610Q 32Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1610Q 32Gb Single Port Fibre Channel Host Bus Adapter

# 64Gb Fibre Channel Host Bus Adapter:

- HPE SN1700Q 64Gb Dual Port Fibre Channel Host Bus Adapter
- HPE SN1700Q 64Gb Single Port Fibre Channel Host Bus Adapter

### Software - System Management

Top

HPE Fiber Channel and Storage Enablement Component for ESXi 8.0

Version: 3.9.0 (Recommended)

Filename: fc-enablement-component\_800.3.9.0.30-1\_20300413.zip

### **Enhancements**

Supports VMware ESXi 8.0

Smart Storage Administrator (SSA) CLI for VMware 8.0

Version: 6.15.11.0 (Recommended)

Filename: ssacli2-component\_6.15.11.0-8.0.0\_20754055.zip

### **Enhancements**

Gen11 PR2 Usage

ROM Flash Universal Firmware Package - HPE ProLiant DL325/DL345 Gen11 (A56) Servers

Version: 1.22\_01-19-2023 (**Recommended**) Filename: A56 1.22 01 19 2023.fwpkg

#### **Important Note!**

**Important Notes:** 

None

**Deliverable Name:** 

HPE DL325 Gen11/DL345 Gen11 Server System ROM - A56

**Release Version:** 

1.22 01-19-2023

**Last Recommended or Critical Revision:** 

1.22\_01-19-2023

**Previous Revision:** 

1.20 01-06-2023

**Firmware Dependencies:** 

None

### **Enhancements/New Features:**

Add new System Configuration (RBSU) configuration options that allow controlling the processor's P0 (maximum) frequency. This includes the "Custom Pstate0" option with settings of "Auto" (default) and "Manual" and the "Pstate0 Frequency(MHz)" option that allows setting the P0 frequency. When the "Custom Pstate0" option is configured for "Manual", the value of the "Pstate0 Frequency(MHz)" is used for the processor's P0 frequency. When the "Custom Pstate0" option is configured for "Auto", the processor uses its normal, maximum P0 frequency and the "Pstate0 Frequency(MHz)" option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties: /redfish/v1/systems/1/bios/settings/CustomPstate0 /redfish/v1/systems/1/bios/settings/Pstate0Frequency

Remove the System Configuration (RBSU) option for "Memory Interleaving Mode". This option is no longer configurable because AMD recommends always enabling this capability for maximum performance. Memory Interleaving will always be enabled with this revision or later of the System ROM no matter how this option had been previously configured. In System Configuration (RBSU), this option had previously been located under the Memory Options. This setting had the following Redfish properties: /redfish/v1/systems/1/bios/settings/AmdMemoryInterleaving

# **Problems Fixed:**

Addressed an issue where system may hang at POST during TPM measurement after restoring manufacturing defaults.

Address an issue where the RegistryVersion format in the URI redfish/v1/registrystore/registries did not follow the Redfish Specification. If scripts were written to conform with the incorrect format in previous System ROMs, those scripts may need to be modified to follow the correct, Redfish compliant format which is implemented in this System ROM revision and later.

Addressed an issue where the System Configuration (RBSU) option "Access Control Service" did not disable PCIe Access Control Service when it's set to disabled.

# **Known Issues:**

None

#### **Fixes**

**Important Notes:** 

None

Firmware Dependencies:

None

**Problems Fixed:** 

Addressed an issue where system may hang at POST during TPM measurement after restoring manufacturing defaults.

Address an issue where the RegistryVersion format in the URI redfish/v1/registrystore/registries did not follow the Redfish Specification. If scripts were written to conform with the incorrect format in previous System ROMs, those scripts may need to be modified to follow the correct, Redfish compliant format which is implemented in this System ROM revision and later.

Addressed an issue where the System Configuration (RBSU) option "Access Control Service" did not disable PCIe Access Control Service when it's set to disabled.

#### **Known Issues:**

None

#### **Enhancements**

Add new System Configuration (RBSU) configuration options that allow controlling the processor's P0 (maximum) frequency. This includes the "Custom Pstate0" option with settings of "Auto" (default) and "Manual" and the "Pstate0 Frequency(MHz)" option that allows setting the P0 frequency. When the "Custom Pstate0" option is configured for "Manual", the value of the "Pstate0 Frequency(MHz)" is used for the processor's P0 frequency. When the "Custom Pstate0" option is configured for "Auto", the processor uses its normal, maximum P0 frequency and the "Pstate0 Frequency(MHz)" option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties: /redfish/v1/systems/1/bios/settings/CustomPstate0 /redfish/v1/systems/1/bios/settings/Pstate0Frequency

Remove the System Configuration (RBSU) option for "Memory Interleaving Mode". This option is no longer configurable because AMD recommends always enabling this capability for maximum performance. Memory Interleaving will always be enabled with this revision or later of the System ROM no matter how this option had been previously configured. In System Configuration (RBSU), this option had previously been located under the Memory Options. This setting had the following Redfish properties: /redfish/v1/systems/1/bios/settings/AmdMemoryInterleaving

ROM Flash Universal Firmware Package - HPE ProLiant DL365/DL385 Gen11 (A55) Servers

Version: 1.22\_01-19-2023 (**Recommended**) Filename: A55\_1.22\_01\_19\_2023.fwpkg

### **Important Note!**

#### **Important Notes:**

None

#### **Deliverable Name:**

HPE DL385 Gen11/DL365 Gen11 Server System ROM - A55

### **Release Version:**

1.22\_01-19-2023

### **Last Recommended or Critical Revision:**

1.22 01-19-2023

### **Previous Revision:**

1.20 01-06-2023

# **Firmware Dependencies:**

None

# **Enhancements/New Features:**

Add new System Configuration (RBSU) configuration options that allow controlling the processor's P0 (maximum) frequency. This includes the "Custom Pstate0" option with settings of "Auto" (default) and "Manual" and the "Pstate0 Frequency(MHz)" option that allows setting the P0 frequency. When the "Custom Pstate0" option is configured for "Manual", the value of the "Pstate0 Frequency(MHz)" is used for the processor's P0 frequency. When the "Custom Pstate0" option is configured for "Auto", the processor uses its normal, maximum P0 frequency and the "Pstate0 Frequency(MHz)" option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties: /redfish/v1/systems/1/bios/settings/CustomPstate0 /redfish/v1/systems/1/bios/settings/Pstate0Frequency Remove the System Configuration (RBSU) option for "Memory Interleaving Mode". This option is no longer configurable because AMD recommends always enabling this capability for maximum performance. Memory Interleaving will always be enabled with this revision or later of the System ROM no matter how this option had been previously configured. In System Configuration (RBSU), this option had previously been located under the Memory Options. This setting had the following Redfish properties: /redfish/v1/systems/1/bios/settings/AmdMemoryInterleaving

#### **Problems Fixed:**

Addressed an issue where system may hang at POST during TPM measurement after restoring manufacturing defaults.

Address an issue where the RegistryVersion format in the URI redfish/v1/registrystore/registries did not follow the Redfish Specification. If scripts were written to conform with the incorrect format in previous System ROMs, those scripts may need to be modified to follow the correct, Redfish compliant format which is implemented in this System ROM revision and later.

Addressed an issue where the System Configuration (RBSU) option "Access Control Service" did not disable PCIe Access Control Service when it's set to disabled.

#### **Known Issues:**

None

# **Important Notes:**

None

### **Firmware Dependencies:**

None

#### **Problems Fixed:**

Addressed an issue where system may hang at POST during TPM measurement after restoring manufacturing defaults.

#### **Fixes**

Address an issue where the RegistryVersion format in the URI redfish/v1/registrystore/registries did not follow the Redfish Specification. If scripts were written to conform with the incorrect format in previous System ROMs, those scripts may need to be modified to follow the correct, Redfish compliant format which is implemented in this System ROM revision and later.

Addressed an issue where the System Configuration (RBSU) option "Access Control Service" did not disable PCIe Access Control Service when it's set to disabled.

#### **Known Issues:**

None

### **Enhancements**

Add new System Configuration (RBSU) configuration options that allow controlling the processor's P0 (maximum) frequency. This includes the "Custom Pstate0" option with settings of "Auto" (default) and "Manual" and the "Pstate0 Frequency(MHz)" option that allows setting the P0 frequency. When the "Custom Pstate0" option is configured for "Manual", the value of the "Pstate0 Frequency(MHz)" is used for the processor's P0 frequency. When the "Custom Pstate0" option is configured for "Auto", the processor uses its normal, maximum P0 frequency and the "Pstate0 Frequency(MHz)" option is not configurable. In System Configuration (RBSU), these options are located under the BIOS/Processor Options. This setting has the following Redfish properties: /redfish/v1/systems/1/bios/settings/CustomPstate0 /redfish/v1/systems/1/bios/settings/Pstate0Frequency

Remove the System Configuration (RBSU) option for "Memory Interleaving Mode". This option is no longer configurable because AMD recommends always enabling this capability for maximum performance. Memory Interleaving will always be enabled with this revision or later of the System ROM no matter how this option had been previously configured. In System Configuration (RBSU), this option had previously been located under the Memory Options. This setting had the following Redfish properties: /redfish/v1/systems/1/bios/settings/AmdMemoryInterleaving

Get connected

hpe.com/info/getconnected

© Copyright 2023 Hewlett Packard Enterprise Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HPE products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional

**Hewlett Packard** Enterprise

Current HPE driver, support, and security alerts delivered directly to your desktop

Trademark acknowledgments, if needed.

Updated April 11 2023

warranty. HPE shall not be liable for technical or editorial errors or omissions contained herein.